

TB-135241 / May 13, 2020

NEW software for FU80, QS80 and NF80

Product:	000-10183-001, 000-10184-001, 000-10185-001
Product Description:	FU80, QS80 and NF80 autopilot remote controller
Software Version:	1.3.02.00.swup
Effective Date:	01.05.2020
Inspect/Update Current Inventory:	Yes

Autopilot remote controllers, FU80, QS80 and NF80 Software Update

We have received reports regarding FU80, QS80 and NF80 autopilot remote controllers that have stopped working – maybe after months of operation.

After advanced testing in-house and aboard vessels, we are pleased to announce the availability of a software update that corrects the problem, which would only occur after 1,193 hours of continuous operation.

Software changes:

- Fixes an issue which causes keys to be non-responsive and causes the screen to only be partially updated, or in some cases totally blank.



Software upgrade

FU80, QS80 and NF80 units in stock at factory or LC's will be upgraded.

The software upgrade can be done by using the Simrad SWUP upgrade tool (ST10) or MFD's and units with a USB or SD card reader.

The new software can be found on Navico-commercial.com web sites for download.

For more information:

Order Support: (800) 324-4737 x4702

Technical support: (918) 438-8668

You may also send any inquiries via email to the addresses listed below, according to your sales-group classification:

- orders@navico.com
- cmd.service@navico.com