

TB-132789 / February 26, 2020

HOOK Reveal Software Update

Product:	All HOOK Reveal
Product Description:	All HOOK Reveal
Software Version:	19.3.1-63.2.4
Effective Date:	Feb 6 2020
Inspect/Update Current Inventory:	Yes

We have discovered an issue where SideScan functionality is inadvertently displayed on some HOOK Reveal SplitShot models – which are not capable of running SideScan – when they are switched into Retail or Demo modes. This software upgrade (19.3.1-63.2.4) corrects that issue.

For More Information:

U.S. Based Resellers Technical and Order Support: (800) 324-4737
Canada Based Resellers Technical Support: (855) 361-1564

You may also send any inquiries via email to the addresses listed below, according to your sales-group classification:

- OEM/Boatbuilder – oem-bb@navico.com
- International/Latin America – international@navico.com
- National Retail – retail@navico.com
- Dealers/Distributors – orders@navico.com